## PRINTED: 01/11/2011 DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 B. WING 155049 01/06/2011 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1630 S COUNTY FARM RD MILLER'S MERRY MANOR WARSAW, IN 46580 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETION PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG REGULATORY OR LSC (DENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) K 000 INITIAL COMMENTS K 000 A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 01/06/11 Facility Number: 000017 RECEIVED Provider Number: 155049 AIM Number: 100273830 JAN 2 4 2011 Surveyor: Amy Kelley, Life Safety Code Specialist LONG TERM CARE DIVISION At this Life Safety Code survey, Miller's Merry INDIANA STATE DEPARTMENT OF HEALTH Manor was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2. This one story facility with a partial basement was determined to be of Type V (000) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in corridors. areas open to the corridors and single station battery operated smoke detectors in the resident rooms. The facility has a capacity of 137 and had a census of 104 at the time of this survey. Quality Review by Robert Booher, REHS, Life

Safety Code Specialist-Medical Surveyor on

aforementioned regulatory requirements as

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

DM WIXMOR

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

		AND HUMAN SERVICES  & MEDICAID SERVICES			PRINTED: 01/11/2011 FORM APPROVEE OMB NO. 0938-0391			
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  155049		(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01		(X3) DATE SURVEY COMPLETED				
		B. WING	B. WING 01/06/2011					
NAME OF PROVIDER OR SUPPLIER				STREET ADDRESS, CITY, STATE, ZIP CODE				
MILLER'S MERRY MANOR				1630 S COUNTY FARM RD WARSAW, IN 46580				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	FÉMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)						
K 000	Continued From page 1		Koo					
	evidenced by the following: K 038 NFPA 101 LIFE SAFETY CODE STANDARD SS=D:			our credible allegation of compliance.				
00 2	Exit access is arranged so that exits are readily accessible at all times in accordance with section 7.1. 19.2.1			K038				
	This STANDARD is Based on observation failed to ensure 1 of discharge paths was times. This deficient in the laundry room in Findings include:  Based on an observation of Supervisor and the Don 01/06/11 at 12:57 the laundry room was	readily accessible at all practice could affect all staff in the event of an emergency.  Ition with the Maintenance irector of Support Services p.m., the rear exit door in blocked by portable was acknowledged by the		The portable shelving cart blorear door exit in the laundry removed on 1/7/11. No resid affected by this deficient pracresidents potentially exiting the via the rear door exit in the laroom could have been affected deficient practice. All facility exit discharge pathways will be checked for blockage on a we basis for 4 weeks, then month thereafter using a Preventative Maintenance Form (see attach & any findings will be added to Quality Assurance Program. Maintenance Supervisor or details be responsible.  Completion Date: 2/5/11	ents were ents were ents were ents were entice. All he facility undry d by this exterior be ekly ly entert A) to the The			
K 062 SS=F	NFPA 101 LIFE SAFE Required automatic s continuously maintain condition and are insp	ed in reliable operating	K 062	:				
				:	:			

		AND HUMAN SERVICES				D: 01/11/2011 MAPPROVED			
CENTERS FOR MEDICARE STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MU A. BUILI	LTIPLE CONSTRUCTION DING 01	(X3) DATE	OMB NO. 0938-0391 (X3) DATE SURVEY COMPLETED			
		155049	B. WING		01/6	06/2011			
NAME OF PROVIDER OR SUPPLIER MILLER'S MERRY MANOR			S	STREET ADDRESS, CITY, STATE, ZIP CODE 1630 S COUNTY FARM RD WARSAW, IN 46580					
(X4) ID PREFIX TAG	: (EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE AP DEFICIENCY)	IOULD BE	(X5) COMPLETION DATE			
	Continued From page 2 This STANDARD is not met as evidenced by: Based on record review and interview, the facility failed to ensure 2 of 2 sprinkler systems were maintained in proper working order. Once obstructive material is observed during an investigation as described in NFPA 25, the Standard for the Inspection, Testing and Maintenance of Water-Based Fire Protection Systems at 10-2.1., NFPA 25, 10-2.3 requires a complete flushing program shall be conducted. The work shall be done by qualified personnel. This deficient practice affects all occupants.  Findings include:  Based on record review with the Maintenance Supervisor and the Director of Support Services on 01/06/11 at 11:25 a.m., the "Service Call Report" from the SafeCare interior pipe inspection on the sprinkler systems stated, "I checked crossmains above rms 8,23,9 on country manor Both systems need to be flushed". Based on an interview with the Maintenance Supervisor at the time of record review, there has not been a sytem flush on either of the systems.  3.1-19(b)								